SUMMARY STATUS OF CMARP TASKS . July 17, 1998

TASK 1 – REFINE GOALS, OBJECTIVES AND NEEDS

Responsible Persons - Bellory Fong and Bruce Herbold

TASK 2 – DEVELOP A CONCEPTUAL FRAMEWORK

Responsible Persons - Fred Nichols and Randy Brown

TASK 3 – MONITORING PROGRAM DESIGN

Sub-Task 3A – Inventory Existing Monitoring Programs

Sub-Task 3B – Develop Monitoring Elements

Element 1 – Ecosystem (Restoration Plan)

Responsible Persons – Larry Brown, Bruce Herbold, Pete Rhoads, Serge Birk

Sub-Element 1A – Bay-Delta fish /X2 relationships

Team Lead - Bill Bennett

Sub-Element 1B – Shallow water habitat and terrestrial interface

Sub-Element 1C – Hydrodynamics and transport support

Team Lead - Steve Monismith

Sub-Element 1D – System productivity (other than fishes and

large invertebrates)

Team Lead - Wim Kimmerer

Sub-Element 1E – System productivity (fish and large

invertebrates, coordinates with X2)

Team Lead - Kathy Heib

Sub-Element 1F - Contaminants

Team Lead - Bruce Thompson

Sub-Element 1G – Delta smelt

Team Lead - Bill Bennett

Sub-Element 1H – Striped bass

Team Lead - Lee Miller

Sub-Element 1I – Other Species (resident and migratory) Team Lead – Ted Sommer

Sub-Element 1J – River Systems – Salmon IEP Central Valley Team

Sub-Element 1K – Resident fishes (including steelhead and lamprey)

Sub-Element 1L – Fluvial geomorphology and riparian issues Team Lead – John Williams

Sub-Element 1M – Benthic invertebrates Team Lead – Jim Harrington

Element 2 – Water Quality
Responsible Person – Leo Winternitz

Sub-Element 2A – System Productivity Team Lead – Wim Kimmerer

Sub-Element 2B – Contaminants Team Lead – Bruce Thompson

Sub-Element 2C – Drinking Water Quality Team Lead – Phil Wendt/Rich Bruer

Element 3 - Water Transfers
Responsible Person – Larry Smith (Temp.)

Element 4 – Water Use Efficiency Responsible Person – Larry Smith (Temp.)

Element 5 – Watershed Management Responsible Person – Peter Stine

Element 6 – Delta Levees Responsible Person – Larry Smith (Temp.)

Sub-Task 3C – Develop a Process for Data Management Responsible Person – Karl Jacobs

Sub-Task 3D – Develop a Process for Data Assessment and Reporting Responsible Person – Peter Stine

20/1 0

Sub-Task 3E – Category III Monitoring Institutional Process Responsible Persons – Leo Winternitz and Jeff Phipps

TASK 4 – DESIGN A CALFED FOCUSED RESEARCH PROGRAM Responsible Person – Larry Smith (Temp.)

TASK 5 – DEVELOP AN INSTITUTIONAL STRUCTURE FOR CMARP Responsible Person – Margaret Johnston

LHW - 7/16/98